

November 12, 2003

## Dates when Luxfer changed its aluminum alloy from 6351 to 6061

Between 1987 and 1988, Luxfer Gas Cylinders discontinued use of 6351 aluminum alloy and began using a proprietary version of 6061 aluminum alloy for all its aluminum cylinder models. Listed below are the dates by model number when the transitions to the new alloy occurred. Any current Luxfer models that do not appear on this list were never made from 6351 alloy in the first place and have always been made from Luxfer's proprietary 6061 alloy.

<b>SCUBA</b>	<b>Change Date</b>	<b>CO2</b>	<b>Change Date</b>
S30, S63	5-88	C1.2, C1.5	1-89
S40	6-88	C2	11-88
S50, S92	4-88	C10	8-88
S72, S100	8-87	C5	6-88
S80	1-88	C15	11-87
S808	5-87	C20, C35	4-88
		C50	2-88
<b>SCBA</b>	<b>Change Date</b>	<b>MEDICAL</b>	<b>Change Date</b>
L7, L8, L13	9-87	M9	1-88
L13	5-88	MD15, ME24	12-87
L15	1-89		
L26	2-88		
L45	11-87	<b>INDUSTRIAL GAS</b>	<b>Change Date</b>
		N22, N150	5-88
		N33	11-88
		N60, N122	12-87
		N88	12-88